Approved For Release 2001/03/17 : CIA-RDP82-00457R004000250006-8 Soviet Zone of Germany COUNTRY ... REPORT NO. TCPIC GROSSENHAIN Airfield 25X1X6 2 ENCLOSURES (NO. & TYPE) REMARKS\_\_\_\_\_ ----- RETURN TO CIA LIBRARY 25X1X6 7 October 1949 The GROSSENHAIN (N 52/A Ol) airfield was unoccupied. According to a worker employed there, the scheduled 1,300-foot extension of the runway toward ADELSDORF (N 52/A 01) was temporatily stopped. Only 50 of the 700 workers were still at the field. The old sections of the two runways had been carred but the newly constructed sections had an 8-inch concrete surface on a 12-inch gravel layer. The ammunition cantonment buildings on the northern edge of the field had been vacated. 13 October 1949 2. A guard detail of 20 Soviet Air Force soldiers arrived. 14 October 1949 25X1C The truck loaded with furniture left the field. 19 October 1949 Eighteen to twenty Soviet of ficers inspected the runways and air field buildings. 21 October 1949 The field was still unoccupied. Forty laborers did grading work. 25X1X6 20 October 1949 No aircraft were parked at the field and the hangars were closed. A fuel dump with underground containers was located on the western edge of the field, north of the airfield buildings. A second and larger fuel dump was on the northern edge. A road was under construction between the two CLASSIFICATION SPECKET-CONTROL/US OFFICIALS ONLY This document is hereby regraded to Document CONFIDENTIAL in accordance with the No Change letter of 13 October 1978 from the Director of Central Intelligence to the Declassift d Archivist of the United State Release 2001/03/17 : CIA

TO MAY Da'e: 3 24 Bu:

2

25X1A2g

dumps. These dumps and the airfield buildings were guarded by Soviet Air Force sentries. The truck E 5-36-77 and another truck without number left the field. The construction work on the runways, guarded by Feople's Folice was still under way. The E-W concreted and tarred runway, about 230 feet wide, had been extended to the road to ELSTEHWERDA (N 52/A 03).

7. Empty ammunition containers, each about 32 inches long and 6 inches in diameter, were stored on the loading ramp. Five closed railroad boxcars and one railroad tank car were being shunted on the spur track. Extensive excavation work for an unidentified purpose was being done near the leading ramp.

## 25X1A Comment:

- a. According to this report, one runway was extended up to the road to ELSTERLERDA on the west but the extension work on the second runway toward N-E was apparently temporarily stopped.
- b. Report confirms that the field is not occupied by an air unit. The grading work under way and the reported inspection of the field by officers indicate that the field is probably intended to be reoccupied.
- c. The motor vehicle are 25X1C presumably assigned to the airfield construction unit previously employed at the field.

SPORTT-CONTROL/US OFFICIALS ONLY

